



Do not tighten too much a few drips OK




Fill from bottom

Not too tight



Close Valve and you are ready to go



Record drop in mm for time interval

We need mm drop per minute



Measure depth of auger hole and record on baggie

